Map ID MAP FINDINGS

Direction Distance

Distance Elevation Site EDR ID Number

EDR ID Number

EDR ID Number

 1206
 MANHOLE 62762
 NY Spills
 S106736569

 NNW
 STILLWELL AVE. & 24TH AVE
 N/A

> 1 BROOKLYN, NY

1.575 mi. 8317 ft.

Relative: SPILLS:
Higher Name: MANHOLE 62762

Actual: Address: STILLWELL AVE. & 24TH AVE

20 ft. City,State,Zip: BROOKLYN, NY Spill Number/Closed Date: 0410831 / 2005-06-03

 Facility ID:
 0410831

 Facility Type:
 ER

 DER Facility ID:
 271192

 Site ID:
 335884

 DEC Region:
 2

Spill Cause: Unknown
Spill Class: C4
SWIS: 2401
Spill Date: 2005-01-03
Investigator: GDBREEN
Referred To: Not reported
Reported to Dept: 2005-01-04

CID: 74

Water Affected: Not reported Unknown Spill Source: Spill Notifier: Other Cleanup Ceased: Not reported Cleanup Meets Std: False Not reported Last Inspection: Recommended Penalty: False **UST Trust:** False Remediation Phase:

Date Entered In Computer: 2005-01-04
Spill Record Last Update: 2005-06-03
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller Company: 999
Contact Name: ERT DESK

DEC Memo:

"03-JAN-2005 09:50 HRS. UNDERGROUND DEPT.SPLICER J.PETERSON EMP# 87551 REPORTS: WHILE ON LOCATION FOR MAINTENCE WORK FOUND: APPROX. 2 GAL OF UNKNOWN OIL ON APPROX. 100 GAL'S OF WATER. NO SEWERS OR WATERWAYS APPEAR TO BE AFFECTED. THERE IS NO FIRE INVOLVEMENT. NO SMOKE INVOLVEMENT. THERE WERE NO INJURIES RELATED TO THIS INCIDENT. THERE ARE NO INCLEMENT WEATHER CONDITIONS OR HAZARD THAT CONTRIBUTED TO THIS SPILL. NO PRIVATE PROPERTY AFFECTED. OWNER OF SUBSTANCES IS UNKNOWN. NO KNOWN SUMP OR PUMP. NO KNOWN SUBSTANTIAL CRACKS IN STRUCTURE. ENIVIR. TAG# 34973 PLACED. 1 LIQ. SAMPLE TAKEN FROM SPILL & MARKED PRIORITY E . 24 HR DEMINIMIS CHAIN OF CUSTODY# DD-05029. SAMPLE TO BE TAKEN TO ASTORIA CHEM. LAB C.HOGAN 07511 LAB RESULT RECEIVED 1/3/05 - 2110. 05-00022. <1.0 PPM. TJ - 50495 UPDATE: 1/4/05 - 0100 C. FERNANDEZ - O.S. - ENV. OPS., REPORTS NO STRUCTURE OF ANY KIND ON THE S/W/C OF STILLWELL AVE & 24 AVE (WHICH WOULD BE MISTAKEN FOR THE S/E/C IF STILLWELL RAN EAST & WEST WHICH IT DOESN'T). I

CHECKED THE C & D PLATES AND FOUND MH62763 ON THE S/S OF HIGHLAWN AVE

20' E/O STILLWELL AVE (FAIRLY CLOSE TO THE S/E/C). MR. FERNANDEZ CHECKED THAT MH AND FOUND NEW CABLE IN THE STRUCTURE. HE ALSO CHECKED SB64878 OPP THE N/W/C OF 24 AVE & 81 ST (ON STILLWELL AVE) AND FOUND NEW CABLE IN THAT STRUCTURE. SINCE WE FOUND NO ENVIRONMENTAL TAG IN

Map ID MAP FINDINGS

Direction Distance Elevation

EDR ID Number
Site Database(s) EPA ID Number

EITHER STRUCTURE, IT WAS DECIDED THAT WE WOULD CLEAN BOTH STRUCTURES AND BRING MR. PETERSON OF THE U.G. OUT THERE TO TELL US WHERE HE PLACED THE TAG. THE 24 HR CLOCK FOR THIS INCIDENT RUNS OUT AT 0945. THIS WILL ENABLE US TO CLOSE THIS OUT IF WE HAPPENED TO CLEAN THE RIGHT STRUCTURE OR TAKE IT OFF THE 24 HR CLOCK IF MR. PETERSON PLACED THE TAG IN SOME OTHER STRUCTURE. INCIDENT REMAINS OPEN UNTIL THEN. TJ - 50495 UPDATE: 1/4/05 - 0220. K. HUFFORD - ENV. OPS., REPORTS CLEANUP OF SB64878 COMPLETED BY DOUBLE WASHING STRUCTURE WITH BIO GEN 760. NO TAG FOUND. UPDATE: 1/4/05 - 0430. K. HUFFORD - ENV. OPS., REPORTS CLEANUP OF MH62763 (HIGHLAWN AVE & STILLWELL AV) COMPLETED BY DOUBLE WASHING STRUCTURE WITH BIO GEN 760. SUMP IN STRUCTURE FOUND SEALED. NO TAG FOUND. TJ - 50495 1/04/2005 06:40 HRS. -- BROOKLYN ENV OPS O/S C. FERNANDEZ REPORTS HE CHECKED WITH UNDERGROUND AND THE

MANHOLE NUMBER AND LOCATION GIVEN ON ORIGINAL INCIDENT REPORT (M-62763 S/E/C STILLWELL AVE & 24 AVE) IS INCORRECT. ACTUAL MANHOLE/LOCATION IS: M-62762 OPP. S/E/C STILLWELL AVE & 24 AVE. FERNANDEZ ALSO REPORT CLEANUP WILL NOT BE COMPLETED BY 09:45 HRS. DUE TO A CAR OVER THE MANHOLE. INCIDENT REMOVED FROM 24-HOUR DEMINIMIS AND CIG WILL BE NOTIFIED. 1/04/2005 07:00 HRS. -- NOTIFIED R. ELLIOTT OF C.I.G. -- W.W. #17344 UPDATE 06-JAN-2004 1845 STRUCTURE LOCATON UPDATED ON REPORT, INFO FROM WAREHOUSE.. W/S STILLWELL AVENUE, 20' N/O 24TH AVENUE UPDATE 06-JAN-2005 19:20 HRS. ENVIR. OPER MECH-A S.ADEDAPO REPORTS: DISCOVERED AN EARTHEN SUMP, AND WILL SEAL SAME. UPDATE 06-JAN-2005 2018HRS FLUSH OPERATIONS MECHANIC D. LICHTENSTEIN REPORTS TANKER REMOVED APPX 1900 GALS OF LIQUID FROM THE STRUCTURE. CREW DBLE WASHED STRUCTURE WITH BIO-GEN760, EARTHEN SUMP WAS SEALED BY THE CREW, TAG NO. 34973 WAS VERIFIED IN THE STRUCTURE PRIOR TO THE INITIATION OF THE CLEAN UP, HOWEVER, INADVERTENTLY TAKEN UP BY THE VACTOR. CLEANUP IS 100'

Remarks: "2 gallons of unknown oil on 100 gallons of water in manhole. Cleanup is pending access manhole - car over manhole. Ref. 156757"

All Materials:

 Site ID:
 335884

 Operable Unit ID:
 1097942

 Operable Unit:
 01

 Material ID:
 578106

 Material Code:
 0066A

Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: 2.00
Units: G
Recovered: .00

Oxygenate: Not reported